



SCRUT AUTO

SCRUT CERTIFIED VEHICLE
120 POINT INSPECTION CHECKLIST

REG. NO: 1240CC
MAKE: FIAT
MODEL: 500
CHASSIS NO: ZFA31200003C57887
ODOMETER: 16001
INSPECTED BY: SYAHRUL ERMAN
DATE: 24/01/2024

This inspection is conducted in accordance with our professional opinions and ethics at SCRUT AUTO SDN. BHD.
We are not responsible for any issues that may arise after this certificate is issued.
The inspection certificate we issued cannot be used for any legal claim or action.

QUALIFICATION STANDARDS

1 Vehicle history report pulled & provided by:
None

BAD	MOD	GOOD	
0	0	20	0

2 Odometer is actual kmh/miles*

-25	0	50	50
-----	---	----	----

3 No branded or salvaged title

-25	0	50	50
-----	---	----	----

4 No known frame damage per vehicle history report*

-25	0	50	50
-----	---	----	----

5 No visible damage that would substantially impact the safety of the vehicle*

-25	0	50	50
-----	---	----	----

6 No visible performance modifications

-2	2	4	4
----	---	---	---

7 No visible suspension modifications

-2	2	4	4
----	---	---	---

8 No visible exhaust modifications

-1	1	2	2
----	---	---	---

9 List stored codes: Refer Picture

-5	5	10	5
----	---	----	---

Max Points: 240

POINTS: 215

MECHANICAL STANDARDS: PRE-ROAD TEST

Underhood Checks:

*all items are operational & properly functioning

BAD	MOD	GOOD	
-----	-----	------	--

-1	1	2	2
----	---	---	---

-1	1	2	1
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	2
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	1
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	1
----	---	---	---

-2	2	4	2
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	2
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	1
----	---	---	---

-2	2	4	2
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

MECHANICAL STANDARDS: PRE-ROAD TEST

Operational & Functional Checks (cont.):

38 Overhead console

39 Heated seats

40 Cool seats

41 Heating system

42 Air conditioning*

43 Turn Signals*

44 Hazard lamps*

45 Horn*

46 Brake lamps*

47 Headlamps*

48 High beam*

49 Low beam*

50 Interior lamps

51 All power windows

52 Parking brake*

53 Fog lamps

54 Windshield wiper system*

55 Wiper blades in good condition

56 Rear wiper in good condition

57 Rearview mirror*

58 Sideview mirrors*

59 Rear defroster

60 Seat belts*

61 Tilt steering wheel

62 Sunroof

63 Convertible top

64 All manual switches

65 All factory installed options working properly

Max Points: 110

Under vehicle:

66 Transmission is free of cracks & leaks*

67 Transmission seal is free of cracks & leaks*

68 Transfer case (when applicable) is free of cracks & leaks*

69 Rear axle case is free of cracks & leaks*

70 Front axle (when applicable) is free of cracks & leaks*

71 All structural components are free of impact damage*

72 Exhaust system free from damage & leaks*

73 Catalytic converter in place

Max Points: 64

BAD	MOD	GOOD	
-----	-----	------	--

-1	1	2	2
----	---	---	---

-1	1	2	2
----	---	---	---

-1	1	2	2
----	---	---	---

-1	1	2	2
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	2
----	---	---	---

-1	1	2	2
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	2
----	---	---	---

-2	2	4	4
----	---	---	---

-2	2	4	4
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

POINTS: 106

BAD	MOD	GOOD	
-----	-----	------	--

-5	5	10	5
----	---	----	---

-5	5	10	5
----	---	----	---

-5	5	10	5
----	---	----	---

-5	5	10	5
----	---	----	---

-5	5	10	5
----	---	----	---

-5	5	10	5
----	---	----	---

-1	1	2	1
----	---	---	---

-1	1	2	1
----	---	---	---

POINTS: 32

TIRE STANDARDS

- 74 FRONT: Both matching brand & size
75 REAR: Both matching brand & size
76 Tread depth must be of 5/32" or greater
77 Wheels & tires must be within factory recommended sizes
78 *Tires are free of bubbles & major cracks**
79 *Wheels are free of major cracks & damage**
80 Tires are properly inflated

BAD	MOD	GOOD	
-1	1	2	1
-1	1	2	1
-1	1	2	1
-2	2	4	2
-2	2	4	2
-2	2	4	2
-1	1	2	1

Max Points: 20

POINTS: 10

BRAKE STANDARDS

- 81 *Parking brake & cables are free of*
seizing & are operational*
82 *Brake rotors & drums are free of*
rust, scoring, pitting or deep gouges*

BAD	MOD	GOOD	
-5	5	10	5
-5	5	10	5

Max Points: 20

POINTS: 10

SUSPENSION STANDARDS

- 83 *Shock absorbers/struts**
84 *Coil springs/leaf springs**
85 *Sway bars**
86 *Control arms**
87 *Ball joints**

BAD	MOD	GOOD	
-5	5	10	10
-5	5	10	10
-5	5	10	10
-5	5	10	10
-5	5	10	10

Max Points: 50

POINTS: 50

EXTERIOR CONDITION

- 88 *No evidence of flood, fire or major hail damage**
89 Grill trim, & roof rack are in place & secure
90 Bumpers are in place & secure
91 *Body panel damage? If so, please list:**

BAD	MOD	GOOD	
-5	5	10	10
-1	1	2	2
-1	1	2	2

none

-2	2	4	2
----	---	---	---

- 92 *Glass is free of cracks & major chips**
93 Headlights are free of damage & moisture
94 *Headlights are all working**
95 Brake lights are free of damage & moisture
96 *Brake lights are all working**
97 *All turn signal lights are working**

-2	2	4	4
-2	2	4	4
-2	2	4	4
-1	1	2	2
-2	2	4	4
-2	2	4	4

- 98 *Any other obvious signs of damage? If so, please list:**

none

-5	5	10	5
----	---	----	---

Max Points: 50

POINTS: 43

INTERIOR CONDITION

- 99 Headliner intact
100 No major rips or tears in seating
101 All handles & knobs are intact & present
102 *All required seatbelts are intact**
103 *All seatbelts functioning**
104 List any missing equipment please:

none

Max Points: 12

BAD	MOD	GOOD	
-1	1	2	2
-1	1	2	2
-1	1	2	2
-1	1	2	2
-1	1	2	2

-1	1	2	1
----	---	---	---

POINTS: 11

ROAD TEST

- 105 No abnormal wind noise
106 *Engine is operating properly & no*
obvious signs of problems*
107 *Engine oil pressure are within*
normal range levels*
108 *Temperatures are within normal*
range levels*
109 *Clutch is operating properly*
110 *Transmission is shifting properly*
111 *Vehicle is free of vibrations &/or*
unusual noises of any kind*
112 Air conditioning & heating working
properly on all settings
113 *Gear selector operating**
114 Steering wheel aligned
115 *Anti-lock brake system working properly**
116 *Overall stopping performance is good**
117 *Vehicle alignment within specifications**

Max Points: 46

Equipment operation:

- 118 Cruise control & Overdrive
119 Instrument panel/gauges
120 Sound and/or entertainment system

Max Points: 8

BAD	MOD	GOOD	
-1	1	2	2
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-1	1	2	2
-2	2	4	4
-1	1	2	2
-2	2	4	4
-2	2	4	4
-2	2	4	4

-1	1	2	2
-2	2	4	4
-1	1	2	2

POINTS: 46

-1	1	2	2
-2	2	4	4
-1	1	2	2

POINTS: 8

GRADE	EXCELLENT	FINE	GOOD	FAIR	WORST
	600-670 pts	500-599 pts	270-499 pts	135-269 pts	0-134 pts
A	Perfect with original new component	Extremely well-maintained	Well-done maintained with	Average and need maintenance	Not fit for roadworthy conditions

CUSTOMER SIGNATURE

BY SIGNING THIS FORM I CERTIFY THAT I HAVE RECEIVED:

- A COPY OF MY VEHICLE HISTORY REPORT.
- A COPY OF MY 125 POINT INSPECTION CHECKLIST AND UNDERSTAND WHAT MY LIMITED WARRANTY IMPLIES.

Signature _____

Date _____

*ASK HOW YOU CAN UPGRADE AND EXTEND YOUR CERTIFIED WARRANTY.

RESULT POINTS

576 / 670



Spare Tyre ok
Emergency tools kit complete



Good condition



Engine and gearbox
good condition



Original mileage



ZFA3120000JC57887



Tyre year made
2019



ZFA3120000JC57887



Battery And Charging
system ok



Brake fluid ok



Front Suspension Ok







**SCRUT
VERIFIED!**

ZFA3120000JC57887



**SCRUT
VERIFIED!**

ZFA3120000JC57887





