



SCRUT AUTO

SCRUT CERTIFIED VEHICLE
120 POINT INSPECTION CHECKLIST

REG. NO: ZAREAEKNSJ7574309
MAKE: ALFA ROMEO
MODEL: GIULIA
CHASSIS NO: ZAREAEKNSJ7574309
ODOMETER: 7081
INSPECTED BY: SYAHRUL ERMAN
DATE: 21/11/2023

This inspection is conducted in accordance with our professional opinions and ethics at SCRUT AUTO SDN. BHD.
We are not responsible for any issues that may arise after this certificate is issued.
The inspection certificate we issued cannot be used for any legal claim or action.

QUALIFICATION STANDARDS

1 Vehicle history report pulled & provided by:

None

BAD	MOD	GOOD
0	0	20
0	0	0

2 Odometer is actual kmh/miles*

-25	0	50
-25	0	50
0	0	50

3 No branded or salvaged title

-25	0	50
-25	0	50
0	0	50

4 No known frame damage per vehicle history report*

-25	0	50
-25	0	50
0	0	50

5 No visible damage that would substantially impact the safety of the vehicle*

-25	0	50
-25	0	50
0	0	50

6 No visible performance modifications

-2	2	4
-2	2	4
0	2	4

7 No visible suspension modifications

-2	2	4
-2	2	4
0	2	4

8 No visible exhaust modifications

-1	1	2
-1	1	2
0	1	2

9 List stored codes: Refer Picture

-5	5	10
-5	5	10
0	5	10

Max Points: 240

POINTS: 165

MECHANICAL STANDARDS: PRE-ROAD TEST

Underhood Checks:

*all items are operational & properly functioning

10 Hood release is in working condition

BAD	MOD	GOOD
-1	1	2
-1	1	2
0	1	2

11 Brake fluid is clean & full

-1	1	2
-1	1	2
0	1	2

12 Brake system is free of leaks*

-2	2	4
-2	2	4
0	2	4

13 Power steering fluid is full

-1	1	2
-1	1	2
0	1	2

14 Power steering fluid is free of contamination and discoloration*

-2	2	4
-2	2	4
0	2	4

15 Wiper/Washer fluid is full

-1	1	2
-1	1	2
0	1	2

16 Chargin system working correctly*

-2	2	4
-2	2	4
0	2	4

17 Intake & exhaust manifolds are free of cracks & leaks*

-2	2	4
-2	2	4
0	2	4

18 Transmission fluid is at prescribed level

-1	1	2
-1	1	2
0	1	2

19 Transmission fluid is clean & free of contamination*

-2	2	4
-2	2	4
0	2	4

20 Head gasket is free of leaks*

-2	2	4
-2	2	4
0	2	4

21 Radiator coolant is at the prescribed level

-1	1	2
-1	1	2
0	1	2

22 Radiator is free of leaks*

-2	2	4
-2	2	4
0	2	4

23 Radiator coolant tested to 80 (in degrees +/-)

-1	1	2
-1	1	2
0	1	2

24 Belts are free of cracks, buldges & frays*

-2	2	4
-2	2	4
0	2	4

25 Hoses are free of cracks & leaks*

-1	1	2
-1	1	2
0	1	2

26 Vacuum lines are free of cracks & leaks

-1	1	2
-1	1	2
0	1	2

Max Points: 50

POINTS: 38

Operational & Functional Checks:

27 Operational key*

-2	2	4
-2	2	4
0	2	4

28 Key fob with remote keyless entry working

-1	1	2
-1	1	2
0	1	2

29 All doors open & close properly

-1	1	2
-1	1	2
0	1	2

30 Door locks (all switches)

-1	1	2
-1	1	2
0	1	2

31 Trunk/Liftgate release & latches

-1	1	2
-1	1	2
0	1	2

32 Seat adjusters

-1	1	2
-1	1	2
0	1	2

33 Steering column adjuster

-1	1	2
-1	1	2
0	1	2

34 Ignition switch*

-2	2	4
-2	2	4
0	2	4

35 Malfunction indicators & warning lamps*

-2	2	4
-2	2	4
0	2	4

36 Air bag system*

-2	2	4
-2	2	4
0	2	4

37 Trip computer

-1	1	2
-1	1	2
0	1	2

MECHANICAL STANDARDS: PRE-ROAD TEST

Operational & Functional Checks (cont.):

38 Overhead console

39 Heated seats

40 Cool seats

41 Heating system

42 Air conditioning*

43 Turn Signals*

44 Hazard lamps*

45 Horn*

46 Brake lamps*

47 Headlamps*

48 High beam*

49 Low beam*

50 Interior lamps

51 All power windows

52 Parking brake*

53 Fog lamps

54 Windshield wiper system*

55 Wiper blades in good condition

56 Rear wiper in good condition

57 Rearview mirror*

58 Sideview mirrors*

59 Rear defroster

60 Seat belts*

61 Tilt steering wheel

62 Sunroof

63 Convertible top

64 All manual switches

65 All factory installed options working properly

Max Points: 110

POINTS: 106

Under vehicle:

66 Transmission is free of cracks & leaks*

67 Transmission seal is free of cracks & leaks*

68 Transfer case (when applicable) is free of cracks & leaks*

69 Rear axle case is free of cracks & leaks*

70 Front axle (when applicable) is free of cracks & leaks*

71 All structural components are free of impact damage*

72 Exhaust system free from damage & leaks*

73 Catalytic converter in place

Max Points: 64

POINTS: 52

TIRE STANDARDS

- 74 FRONT: Both matching brand & size
75 REAR: Both matching brand & size
76 Tread depth must be of 5/32" or greater
77 Wheels & tires must be within factory recommended sizes
78 *Tires are free of bubbles & major cracks**
79 *Wheels are free of major cracks & damage**
80 Tires are properly inflated

BAD	MOD	GOOD	
-1	1	2	2
-1	1	2	2
-1	1	2	2
-2	2	4	2
-2	2	4	2
-2	2	4	2
-1	1	2	1

Max Points: 20

POINTS: 13

BRAKE STANDARDS

- 81 *Parking brake & cables are free of*
seizing & are operational*
82 *Brake rotors & drums are free of*
rust, scoring, pitting or deep gouges*

BAD	MOD	GOOD	
-5	5	10	5
-5	5	10	5

Max Points: 20

POINTS: 10

SUSPENSION STANDARDS

- 83 *Shock absorbers/struts**
84 *Coil springs/leaf springs**
85 *Sway bars**
86 *Control arms**
87 *Ball joints**

BAD	MOD	GOOD	
-5	5	10	5
-5	5	10	5
-5	5	10	5
-5	5	10	5
-5	5	10	5

Max Points: 50

POINTS: 25

EXTERIOR CONDITION

- 88 *No evidence of flood, fire or major hail damage**
89 Grill trim, & roof rack are in place & secure
90 Bumpers are in place & secure
91 *Body panel damage? If so, please list:**

BAD	MOD	GOOD	
-5	5	10	10
-1	1	2	2
-1	1	2	2

None

-2	2	4	2
----	---	---	---

- 92 *Glass is free of cracks & major chips**
93 Headlights are free of damage & moisture
94 *Headlights are all working**
95 Brake lights are free of damage & moisture
96 *Brake lights are all working**
97 *All turn signal lights are working**
98 *Any other obvious signs of damage? If so, please list:**

-2	2	4	4
-2	2	4	4
-2	2	4	4
-1	1	2	2
-2	2	4	4
-2	2	4	4

none

-5	5	10	5
----	---	----	---

Max Points: 50

POINTS: 43

INTERIOR CONDITION

- 99 Headliner intact
100 No major rips or tears in seating
101 All handles & knobs are intact & present
102 *All required seatbelts are intact**
103 *All seatbelts functioning**
104 List any missing equipment please:

none

Max Points: 12

BAD	MOD	GOOD	
-1	1	2	2
-1	1	2	2
-1	1	2	2
-1	1	2	2
-1	1	2	2

-1	1	2	1
----	---	---	---

POINTS: 11

ROAD TEST

- 105 No abnormal wind noise
106 *Engine is operating properly & no*
obvious signs of problems*
107 *Engine oil pressure are within*
normal range levels*
108 *Temperatures are within normal*
range levels*
109 *Clutch is operating properly*
110 *Transmission is shifting properly*
111 *Vehicle is free of vibrations &/or*
unusual noises of any kind*
112 Air conditioning & heating working
properly on all settings
113 *Gear selector operating**
114 Steering wheel aligned
115 *Anti-lock brake system working properly**
116 *Overall stopping performance is good**
117 *Vehicle alignment within specifications**

Max Points: 46

Equipment operation:

- 118 Cruise control & Overdrive
119 Instrument panel/gauges
120 Sound and/or entertainment system

Max Points: 8

BAD	MOD	GOOD	
-1	1	2	2
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-2	2	4	4
-1	1	2	2
-2	2	4	4
-1	1	2	2
-2	2	4	4
-2	2	4	4
-2	2	4	4

-1	1	2	2
-2	2	4	4
-1	1	2	2

POINTS: 46

BAD	MOD	GOOD	
-1	1	2	2
-2	2	4	4
-1	1	2	2

POINTS: 8

GRADE	EXCELLENT	FINE	GOOD	FAIR	WORST
	600-670 pts	500-599 pts	270-499 pts	135-269 pts	0-134 pts
A	Perfect with original new component	Extremely well-maintained	Well-done maintained with	Average and need maintenance	Not fit for roadworthy conditions

CUSTOMER SIGNATURE

BY SIGNING THIS FORM I CERTIFY THAT I HAVE RECEIVED:

- A COPY OF MY VEHICLE HISTORY REPORT.
- A COPY OF MY 125 POINT INSPECTION CHECKLIST AND UNDERSTAND WHAT MY LIMITED WARRANTY IMPLIES.

Signature _____

Date _____

*ASK HOW YOU CAN UPGRADE AND EXTEND YOUR CERTIFIED WARRANTY.

RESULT POINTS

521 / 670



Engine and gearbox
good condition



Front Brake pad
50% left




ZAREAEKN5J7574309

Tyre year made
2023



ZAREAEKN5J7574309


Rear Brake pad
85% left









Good condition



Current mileage



Rear Suspension Ok

Overall Undercarriage ok





